

*Lake Michigan*  
*To Buchanan*  
*Lehrer*

August 20, 1976

4400

Mr. Timothy K. Dahlstrand, P.E.  
Soil Testing Services of Wisconsin, Inc.  
540 Lambeau Street  
Green Bay, Wisconsin 54303

**RECEIVED DNR**

**AUG 23 1976**

**Lake Mich. Dist.**

Dear Mr. Dahlstrand:

This letter is to acknowledge receipt, in response to Order Number 2A-75-1045A, of the hydrogeological report for the proposed Lehrer landfill expansion located in Sections 21, 22, T21N, R18E, Town of Buchanan, Outagamie County by the Bureau of Air and Solid Waste Management on August 13, 1976.

You will be informed in the near future of the status of review.

The construction of improvements covered by these plans may not proceed until the approval in writing has been received by the municipality or owner.

If you have any questions, please contact Mr. Robert T. Glebs at 608-266-7055.

Sincerely,  
Bureau of Air and Solid Waste Management

*JJR/VRK*  
John J. Reinhardt, Chief  
Solid Waste Management Section

JJR:bb

cc: Mr. James Lehrer, Lehrer Sanitary Service  
Harris & Associates, Inc.  
→ Lake Michigan District

01029

8-20-76

*Tr Buchanan*  
*Lehrer*

Green Bay


August 10, 1976

4400

TO: Anthony S. Earl - Madison  
FROM: Gary F. Kulibert  
SUBJECT: Jim Lehrer's Landfill Site

Recently this writer and Terry Gardon inspected the Lehrer landfill site to determine if it was operating in compliance with their license. Our inspection was made at approximately 2:00 p.m. on August 3, 1976. There was serious question if he was covering on a daily basis. Therefore, Terry inspected the site at 6:15 p.m. that evening and at 6:15 a.m. the following morning. As a result of these inspections it was determined that solid waste was not being compacted and completely covered after every day of operation.

Presently Mr. Lehrer is being sued by the Attorney General's office for failing to operate a sanitary landfill in conformance with the codes. Would you please notify the Attorney General's office that the violations are continuing.



Gary F. Kulibert  
Solid Waste Mgt. Coordinator

GFK:ct

NOTED:

\_\_\_\_\_ Date \_\_\_\_\_

01028

Outa. Co  
Lehrer  
Landfill

Lake Michigan District Headquarters  
Box 3600  
Green Bay, WI 54303

August 9, 1976

4400

Mr. Ken Schoenike, City Engineer  
City of Kaukauna  
Kaukauna, Wisconsin 54130

Dear Mr. Schoenike:

On August 3, 1976, I inspected the Lehrer landfill site and adjacent area off of 20th Street to determine if leachates were surfacing. We noted an area where water was coming through the side of the hill in a steady stream. This water was tested for specific conductivity. A reading of 4000 was observed. This is a good indication of contaminated water. Right now it's only speculation but it appears that these materials may be leachates from the Lehrer landfill site.

Presently, our Department is in the process of trying to obtain a hydrogeologic report on Mr. Lehrer's landfill site. Once this report is submitted, our Department will be in a better position to determine if these materials are coming from the Lehrer landfill site and possibly how the situation can be corrected.

Very truly yours,

  
Gary F. Kulibert  
Solid Waste Mgt. Coordinator

GFK:ct  
cc: Solid Waste Mgt. - Madison

01027

~~00038~~